Appraisal Update and/or Completion Report

Redacted

File # Redacted 1004D Disaster Insp

The purpose of this report form is to provide the lender/client with an accurate update completion. The appraiser must identify the service(s) provided by selecting the appro		
Property Address Redacted	Unit #	
City Camano Island State	WA Zip Code 98282	
Legal Description Redacted		
Borrower Redacted Contract Price \$ Date		
	ibe) Original Appraised Value \$ Unknown	
Original Appraiser Unknown Comp	pany Name Unknown	
SUMMARY APPRAI	SAL UPDATE REPORT	
Description Description		
	nance transaction.	
SCOPE OF WORK: The appraiser must, at a minimum: (1) concur with the original		
at least the street, and (3) research, verify, and analyze current market data in order to of the original appraisal.	determine if the property has declined in value since the effective date	
HAS THE MARKET VALUE OF THE SUBJECT PROPERTY DECLINED SINCE THE EFFECT	IVE DATE OF THE PRIOR APPRAISAL?	
This form is not appropriate for a "Post Disaster Inspection" because th	e inspecting appraiser has no knowledge of any previous apprasial on	
this property, and thererfore cannot check either box above. See the atta	ched PROPERTY CONDITION REPORT and photo page for observed	
	· · · ·	
I have, at a minimum, developed and reported this appraisal update in accorda	nce with the scope of work requirements stated in this appraisal update	
2. I performed this appraisal update in accordance with the requirements of the U	··	
	n and that were in place at the time this appraisal update was prepared.	
	skeinendelle omen sukinen deke in men om de file	
1 2 11	-	
	ead the appraisal update report, and agree with the appraiser's analysis,	
·	ling but not limited to the appraiser's analysis oninions statements	
	ing, but not initial to, the appraisor o unaryolo, opiniono, otatomonto,	
CERTIFICATIO	N OF COMPLETION	
INTENDED USE: The intended use of this certification of completion is for the lend	er/client to confirm that the requirements or conditions stated in the	
appraisal report referenced above have been met.	•	
INTENDED USER: The intended user of this certification of completion is the lender	r/client.	
HAVE THE IMPROVEMENTS BEEN COMPLETED IN ACCORDANCE WITH THE REQUIRE	MENTS AND CONDITIONS STATED IN THE ORIGINAL	
APPRAISAL REPORT? $\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \$	opinion of market value. THIS SECTION DOES NOT APPLY TO THIS	
REPORT		
APPRAISER'S CERTIFICATION: I certify that I have performed a visual inspection	n of the subject property to determine if the conditions or requirements	
stated in the original appraisal have been satisfied.		
SUPERVISORY APPRAISER'S CERTIFICATION: I accept full responsibility fo	r this certification of completion.	
SIGNA	ATURES	
ADDITIONAL CERTIFICATION: I/we certify that if this report was transmitted as	an "electronic record" containing my "electronic signature " as those	
· · · · · · · · · · · · · · · · · · ·		
	d as if a paper version of this appraisal report were delivered	
	SUPERVISORY APPRAISER (ONLY IF REQUIRED)	
Signature		
·		
	Expiration date of definication of License	
	CLIDED/JICODY ADDD AIGED	
·		
	· · · · · · · · · · · · · · · · · · ·	
SUPERVISORY APPRAISER'S CERTIFICATION: The Supervisory Appraiser certifies and agrees that: 1. I directly supervised the appraiser for this appraisal update assignment, have read the appraisal update report, and agree with the appraiser's analysis, opinions, statements, conclusions, and the appraiser's certification. 2. I accept full responsibility for the contents of this appraisal update report including, but not limited to, the appraiser's analysis, opinions, statements, conclusions, and the appraiser's certification. CERTIFICATION OF COMPLETION		

PROPERTY CONDITION REPORT

Redacted

File #: Redacted 1004D Disaster Insp

Loan #: Redacted	Order #: Redacted	Order Date: 3/25/16	AVM ID #: N/A
Client: Redacted	Inspecto		Inspection Date:
Property Address: Redacted		City: Camano Island	ST: WA ZIP: 98282
Legal Description: Redacted Neighborhood or Project Name: C	Camano Island		Location: Urban 🔀 Suburban 🗌 Rural
			TION ONLY. THIS REPORT IS NOT AN OPINION OF VALUE AND IS PROPERTY AS OF THE DATE OF INSPECTION. BECAUSE NO
INTERIOR INSPECTION WAS PERFORM Able to View Property? Yes	ORMED, IT IS ASSUMED THAT No If no, please explain:	THE INTERIOR CONDITION IS SIM	MILAR TO THE EXTERIOR CONDITION OF THE SUBJECT PROPERTY.
Construction Type: Detached		No Yes Log Home:	No Yes Conforms to Neighborhood? Yes No
Subject Exterior Condition is Average or		Number of Comparable Properties for	
NEIGHBORHOOD INFLUENCES - WITH			CONDITION OF THE IMPROVEMENTS
Overhead Powerlines	X No	Broken Doors/Windows	⋈ No Yes
Commercial/Industrial Uses	No X Yes	Construction in Process	⋈ No
Boarded-up Homes	No Yes	Roof - Damaged/Missing Shingles	∑ No
Rail Road Tracks	No Yes	Structural Damage	No Yes
Freeway/Highway	No Yes	Siding Missing/Damaged	No Yes
Airport/Flight Path Waste Management Facilities	No Yes	Evidence of Fire Damage Evidence of Flood/Water Damage	No
	ommercial use above is a	Garage	Attached Detached None
convenience store/gas station lo		Garage condition avg or above	No Yes N/A
the subject property. No advers		Property Maintenance	Excellent Good Fair Poor
Comments: Appraiser was give		ny disaster of concern by the	
State of Washington, for Sever concern, and the reason for this Based on appraiser observat	e Storms, Straight Line Winds assignment. cions on 3/28/16, no obviou	s, Flooding, Landslides and M s or apparent damage to the	sued on 01/15/2016, which includes Island County in the udslides. The appraiser assumes this is the declaration of property was noted. It is unknown if any of the above incidents, which was Nov. 12 to Nov. 21, 2015, per the
See the attached photo page for	or photos taken on 3/28/16.		
The appraiser did not go onto to in the Front photo.	he property. Observations w	ere from the street only, and fr	om the hillside above the neighborhood which can be seen
•			

Subject Photos - 1004D - 3/28/16

Borrower	Redacted							
Property Address	Redacted							
City	Camano Island	County	/ Island	State	• WA	Zip Code	98282	
I ender	Redacted							





N Side Front





S Side

Street - Subj. to right, out of photo



PropertyTaken from the hillside above neighborhood